





12V POWER ATTP — POWER SUPPLY



$$R_1 = \frac{0.6}{I}$$



$$R_2 = \frac{0.6}{I}$$

$$R_3 = \frac{0.6}{I}$$