


EFFECTS LOOP
from RY2
FX send
LDR11
189V
2M2
418V
V4B
100n
210V
22k
2M2
200n
82k
1M
100k
LOG
SEND
LEVEL
SEND
RETURN
S1/1
MIX
22k
S1/3
3k3
120k
283V
47n
V4A
2,4V
47k
22u
2k2
LOOP ACTIVE
MASTER
LOG
250k
to RY2
FX return
LDR12



Simple Series Effects Loop

Drawn by Philip Rueb

http://www.diyguitaramp.com