


~~M1, M2: Bright caps disconnected.~~ ~~Reinstated, 27/10/09~~
M3: 1M added in parallel = approx 250K. 27/4/08
M4: 180pf removed when it went leaky. 16/7/08
M5: Replaced 100K to ground with 470K. 9/1108
M6: Replaced cabling to Ch1 insert with shielded cable as existing cable was microphonic. 9/11/08
M7: Disconnected bass pot from ground, 27/10/09

Resistors: 1w, CC, 5%
Caps: Met. Poly 5%. Values in uf unless otherwise stated

DC30
Channel 1 & Channel 2 Preamps
9 Nov 2008. I. G. Morris