




IMPROVED BIAS FOR ORIGINAL DR 103 TRANNY
CONTROL FOR
2 PAIR EL34

BIAS POTN'S IN TOP OF CHASSIS