


IMPROVED BIAS FOR ORIGINAL DR 103 TRANNY CONTROL FOR 2 PAIR EL34

BIAS POTM'S IN TOP OF CHASSIS

REV. 1 03-12-2020 ~~JUMPER # 6-13 ADDED~~

REV. 2 06-12-2020 JUMPER 6-13 ADDED